

Title: 8-bit LAN submodule add-on software for Windows 95/98

Useful hints about the LAN submodule add-on software for Windows 95/98
(March 1999)

I m p o r t a n t

(1) This software is absolutely necessary for the proper operation of the Siemens Nixdorf LAN submodule. Without this software network addressing errors occur when several LAN submodule equipped beetles are operated in the same subnet.

For that reason the use of the LAN submodule under these special circumstances was officially forbidden until April 1, 1999. This restriction is now lifted.

(2) This software cooperates with the normal Windows 95/98 network stack (Novell NE2000 adapter plus the appropriate protocols and services), which must be installed before or after this add-on package.

(3) It is not allowed to install more than one NE2000 network adapters.

I n s t a l l a t i o n

Begin the installation by running the self-extracting archive
LANSUB9X.EXE

After all files have been unpacked, a dialog box tells you that the
LAN submodule checker for Windows 95/98
will be installed. Click the "Setup" button to resume.

The necessary driver and service will be arranged, and all files will
be copied into the installation directory
C:\SNI\BEETLE\LAN\LANSUB

(it will be created automatically if it does not exist).

After the successful installation the system has to be rebooted.
Please answer the corresponding dialog box with "Yes".

U n i n s t a l l a t i o n

By running the batch file UNINST.BAT
from the installation directory, the LAN submodule add-on software will
be removed from the system. The directory ...\LANSUB will be kept.

***** IMPORTANT:**

Under normal circumstances it will never be necessary to uninstall this software. Even if you temporarily do not use a Siemens Nixdorf LAN submodule, but another network adapter or no network adapter at all, you should let the add-on software activated. There will be definitely no CPU load once the operating system is up.

T e s t f o r p r o p e r i n s t a l l a t i o n

To test whether the LAN submodule add-on software is correctly installed and working, run the program

LSTEST.EXE

It will tell you if there is a consistent installation or not. If not, you should install this software again (as described above).

Installing a second time over an already (partially) installed system will do no harm.

LANSUB9X.EXE	(76KB)
LIESMICH	(3KB)
README	(3KB)